






1


$F_{v,R,k}$
 $L = 0^\circ$



$F_{v,R,k}$
 $L = 90^\circ$

2


$F_{v,R,k}$
 $L = 0^\circ$



$F_{v,R,k}$
 $L = 0^\circ$

3


$F_{v,R,k}$
 $L = 90^\circ$



$F_{v,R,k}$
 $L = 90^\circ$

4


$F_{v,R,k}$
 $L = 90^\circ$



$F_{v,R,k}$
 $L = 0^\circ$

1


$F_{v,R,k}$
 $L = 0^\circ$



$F_{v,R,k}$

2

$F_{v,R,k}$
 $L = 90^\circ$



$F_{v,R,k}$

